






CP1501R



CP1501R




A x18
Spec: $\varnothing 8 \times 30$




B x12
Spec: $\varnothing 7 \times L30$



C x12
Spec: $\varnothing 15 \times H12$



D x5
Spec: $\varnothing 3.8 \times L38$



E x5
Spec:



F x1
Spec: 4#




G x1
Spec: 10g



H x10
Spec: $\varnothing 17$




I x2
Spec:




1


2




3



4





5

6

